Richmond Refinery LPS Alert - Safety

Steam Hose Failure





LI Number: 25871

Location:

D&R East Richmond Refinery

Contact Information:

Jim Adams CTN 242-3777 ADJD@chevron.com

Plugged Steam Hose





Always remember to do your LPSA – because we care about you!

Incident Description:

D&R employees discovered blockage in a steam hose while using it as a steam lance. The hose vendor determined that some steam hoses with test due dates of 09-01-2014 to 11-15-2014 could be defective. At least 288 hoses were delivered to the Storehouse between August 31, 2011 and November 15, 2011.

Immediate Actions Taken:

- 1) All steam hoses at D&R with those test dates were removed by the vendor and will be replaced.
- 2) An incident investigation is underway.

ACTION REQUIRED

- 1) Find and discontinue use of all steam hoses with test due dates of 09-01-2014 to 11-15-2014 (see photo).
- 2) Place them on pallets on platforms for pickup.
- Contact CTR at 242-4368 if additional hoses are needed.
- 4) Expect replacement hoses on your platforms by 5:00 p.m. on November 20, 2011.



This document is intended for company workforce only. Nothing herein should be construed as a legal determination of causation or responsibility. The company makes no representations or warranties, express or implied, about the thoroughness, accuracy, or suitability of use by others of any of the information contained herein.